Summary
T*he actual test being done here is not documented by Apple.* The error indicates a hardware problem.

Details
T*he check involves RAM testing. The test itself is called a "Mod3 test".*

The test identifies bad RAM chips. In this case the chip is at board location