Backup Tape Drives

Description	Capacity	Product No./ Option No.	PRICE	
1/2-inch Streaming Magnetic Tape Subsystem with HP-IB Includes 1m cabinet.	1600 cpi	**7979A**	**$13,400.**	
Tape drive without cabinet for installation in A1001A cabinet		Opt. 1A4	- 1,000.	
Add-on 7979A tape drive for installation in existing 1m cabinet		Opt. 133	- 1,000.	
Kit to add 7936/7937 to 7979/7980 cabinet		Opt. 137	300.	
Return Credit for 7979A toward C1700A Purchase		**7979AN**	- 3,500.	
1/2-inch Streaming Magnetic Tape Subsystem with HP-IB Includes 1m cabinet.	1600/6250 cpi	**7980A**	22,200.	
Tape drive without cabinet for installation in A1001A cabinet		Opt. 1A4	- 1,000.	
Add-on 7980A tape drive for installation in existing 1m cabinet		Opt. 133	- 1,000.	
Kit to add 7936/7937 to 7979/7980 cabinet		Opt. 137	300.	
Return Credit for 7980A toward C1700A Purchase		**7980AN**	- 4,500.	
1/2-inch Streaming Magnetic Tape Subsystem with HP-IB Includes 1m cabinet.	1600/6250/6250XC cpi	**7980XC**	24,700.	
Tape drive without cabinet for installation in A1001A cabinet		Opt. 1A4	- 1,000.	
Add-on 7980XC tape drive for installation in existing 1m cabinet		Opt. 133	- 1,000.	
Kit to add 7936/7937 to 7979/7980 cabinet		Opt. 137	300.	
Return Credit for 7980XC toward C1700A Purchase		**7980XCN**	- 5,500.	
HP Series 6400 Model 2000DC Data compression (up to 8 Gb) DDS format tape drive with SCSI interface.		**C1520B**	3,150.	
HP Series 6400 Model 2000DC Data compression (up to 8 Gb) DDS format tape drive with SCSI interface.		**C1521B**	4,150.	
7978A to 7978B Upgrade Kit		**88702A**	2,445.	
Add 6250 cpi GCR Format to 7979A		**88703A**	11,400.	
Allows 7936/37 Installation in 7979/80 Cabinet Requires 19512A rackmount kit.		**88704A**	400.	
7980A to 7980XC Upgrade Kit		**88705A**	6,800.	
TAPE DRIVE RETURN CREDITS				
The following upgrade credits are available when trading up to a 7980A or 7980XC tape drive:				
Trade-in Credit		**7970EN**	**$2,000.**	
Trade-in Credit		**7974AN**	3,500.	
Trade-in Credit		**7978BN**	4,500.	

Printers

HP 5000 Model F100 Page Printer--60Hz Includes 16 Mb graphics memory.		C2753A	$190,000.	
HP 5000 Model F100 Page Printer--50Hz Includes 16 Mb graphics memory.		C2754A	190,000.	
HP 5000 Model F100/Turbo Page Printer--60Hz Includes Turbo Controller, 16 Mb graphics memory.		C2753B	200,000.	
HP 5000 Model F100/Turbo Page Printer--50Hz Includes Turbo Controller, 16 Mb graphics memory.		C2754B	200,000.	
HP 5000 Model F135 Page Printer--60Hz Includes Turbo Controller, 16 Mb graphics memory.		C2776A	240,000.	
HP 5000 Model F135 Page Printer--50Hz Includes Turbo Controller, 16 Mb graphics memory.		C2777A	240,000.	
HP 5000 Model F100XP Page Printer--60Hz Includes Turbo Controller, 17-inch wide print, 16 Mb graphics memory.		C2772A	250,000.	

Select a System Support Option. Refer to Table 4 on page 112.