

# Table of Contents

## HP 3000 900 Series Business Systems and Servers

|  |           |   |           |   |            |
|--|-----------|---|-----------|---|------------|
| <b>System Support Options Program</b>                                    | <b>4</b>  | <b>Upgrades (cont'd)</b>  |           | <b>Peripherals and Accessories</b>                                | <b>97</b>  |
| <b>Support Options Features</b>  | 5         | Return Series 950 (32490AN)   | 58        | Cabinet Storage Systems   | 97         |
| <b>Selecting the Appropriate Option</b>                                  | 5         | Return Series 955 (A1109AN)   | 58        | Standalone Cabinets and Peripherals                               | 101        |
| <b>How to Order</b>  | 6         | Return Series 958, 960 (A1701AN)  | 58        | HP-FL Disk Arrays and Accessories                                 | 102        |
| <hr/>  |           |   |           | Optical Storage   | 103        |
| <b>HP 3000 900 Series Business Systems and Servers</b>                   | <b>8</b>  | <b>917-987/150 Family Upgrades</b>  | 59        | Back-up Tape Drives   | 104        |
| Series 917LX (A1770B)  | 8         | <b>9x7 Field Upgrade Path Summary</b>                                     | 60        | Printers  | 104        |
| Series 927LX (A1771C)  | 10        | Upgrade to Series 927LX (A1789B)  | 61        | Terminals   | 108        |
| Series 937LX/RX/SX (A1772B)  | 12        | Upgrade to Series 937LX (A1791B)  | 62        | <hr/>   |            |
| Series 947LX/RX/SX (A1708C)  | 14        | Upgrade to Series 937RX (A2481A)  | 63        | <b>Peripheral Accessories</b>                                     | <b>109</b> |
| Series 957RX/SX (A1709B)   | 16        | Upgrade to Series 937SX (A1790B)  | 64        | Plotter Accessories   | 109        |
| Series 967RX/SX (A1710B)   | 18        | Upgrade to Series 947LX (A1759C)  | 65        | Disk and Tape Drive Accessories                                   | 109        |
| Series 987RX/SX (A2317B)   | 20        | Upgrade to Series 947RX (A2482A)  | 66        | Printer Accessories   | 109        |
| Series 987/150RX/SX (A3004A)   | 22        | Upgrade to Series 947SX (A1792C)  | 67        | Table 4. Peripheral and Peripheral Accessories Support Options    | 112        |
| Series 947 Plus System (A2900A)  | 24        | Upgrade to Series 957RX (A2483A)  | 68        | Table 4.1. System Support Options for A1883A and A1884A           | 116        |
| Series 957 Plus System (A2905A)  | 26        | Upgrade to Series 957SX (A1761B)  | 70        | <hr/>   |            |
| Series 967 Plus System (A2910A)  | 28        | Upgrade to Series 967RX (A2484A)  | 72        | <b>Networking</b>   | <b>117</b> |
| Series 987 Plus System (A2920A)  | 30        | Upgrade to Series 967SX (A1762B)  | 74        | Datacomm and Terminal Controller Products (DTC)                   | 117        |
| Series 987/150 Plus System (A3015A)                                      | 32        | Upgrade to Series 987RX (A3001A)  | 76        | LAN Links   | 120        |
| Series 955 (A1109A/AH)   | 34        | Upgrade to Series 987SX (A2318B)  | 77        | Wide Area Network Links   | 122        |
| Series 960 (A1130A)  | 35        | Upgrade to Series 987/150RX (A3011A)                                      | 79        | Asynchronous PADs   | 125        |
| Series 980/100 (A1134A)  | 37        | Upgrade to Series 987/150SX (A3013A)                                      | 80        | X.25 Switches   | 125        |
| Series 980/200 (A1149A)  | 38        | Upgrade to Series 922LX (A1711B)  | 81        | Modems  | 126        |
| Series 980/300 (A1150A)  | 39        | Upgrade to Series 922RX (A1175B)  | 81        | HP 3000 Terminal/Plotter Cables, Point-to-Point Connections       | 126        |
| Series 980/400 (A1151A)  | 40        | Upgrade to Series 922 (A1177B)  | 81        | ThinLAN Cables and Accessories                                    | 127        |
| <b>Corporate Business Systems</b>  | <b>42</b> | Upgrade to Series 932 (A1176C)  | 82        | EtherTwist Transceiver Family                                     | 128        |
| <b>Structured Solution Bundle</b>  |           | Upgrade to Series 948 (A1742A)  | 82        | HP 3000 HP-IB, HP-FL and INP Cables                               | 128        |
| LAN Manager for the HP 3000 (B2345)                                      | 48        | Upgrade to Series 958 (A1743A)  | 82        | EtherTwist Hub Family   | 128        |
| Table 1. HP 3000 900 Series Business Systems and Servers Support Options | 49        | Series 925 Upgrade (A1016A)   | 83        | HP Bridge Family  | 129        |
| Table 1.1. HP 3000 Corporate Business System Support                     | 51        | Series 935 Upgrade (A1062A)   | 83        | HP Router Family  | 129        |
| Table 1.2. System Support Options -- HP Corporate Business Systems       | 52        | Series 949 Upgrade (A1601B)   | 83        | Network Management  | 130        |
| <hr/>  |           | Series 950 to 955 Upgrade (A1117A)  | 84        | Services  | 131        |
| <b>Upgrades</b>  | <b>54</b> | Series 950 to 960 Upgrade (A1132A)  | 84        | IBM Communications  | 133        |
| <b>Upgrade Credit/Board Upgrade Matrix</b>                               | <b>54</b> | Series 955 to 960 Upgrade (A1133A)  | 84        | End-User Access and Integration                                   | 141        |
| <b>Return Credits</b>  | <b>55</b> | Upgrade to Series 980/100 (A1137A)  | 84        | Table 5. Data Communications Support Options                      | 143        |
| Return MICRO 3000, 3000LX/GX/RX with 2 Mb (32535AN)                      | 55        | Upgrade to Series 980/200 (A1138A)  | 85        | Table 5.1. System Support Options for 30291A                      | 147        |
| Return MICRO 3000XE (32545AN)  | 55        | Upgrade to Series 980/300 (A1139A)  | 85        | <hr/>   |            |
| Return pre-Series II, Series III, 30, 33, 37, 37XE, 250/260 (32459AN)    | 55        | Upgrade to Series 980/400 (A1140A)  | 86        | <b>Software</b>   | <b>148</b> |
| Return Series 39, 39HP, 40, 42, 44, 48 (32542AN)                         | 56        | Upgrade to Corporate Business System (A1810A)                             | 87        | New Software Tiers  | 148        |
| Return Series 42 XP, 52, 58 (32552AN)                                    | 56        | Table 2. 900 Series Upgrades Support Options                              | 89        | Application Integration   | 151        |
| Return Series 64, 68, 70 (A2478AN)                                       | 56        | Table 2.1. System Support Options -- HP Corporate Business System Upgrade | 90        | HP 3000 Languages MPE V and Compatibility Mode                    | 152        |
| Return Series 920, 922LX (A1702AN)                                       | 57        | <hr/>   |           | HP 3000 Languages MPE/iX Native Mode                              | 153        |
| Return Series 925LX, 925 (A1032AN)                                       | 57        | <b>MPE, I/O and Memory Expansion</b>                                      | <b>91</b> | HP 3000 Information Management Tools MPE V and Compatibility Mode | 155        |
| Return Series 922RX, 922 (A1033AN)                                       | 57        | HP 3000 MPE FOS and Media   | 91        | HP 3000 Information Management Tools MPE/iX Native Mode           | 157        |
| Return Series 932, 935 (A1041AN)   | 58        | HP 3000 I/O   | 94        | HP 3000 Office Systems Software                                   | 160        |
| Return Series 948, 949 (A1700AN)   | 58        | HP 3000 Memory Expansion  | 95        | HP Cooperative Computing Solutions                                | 164        |
|  |           | Table 3. MPE, I/O and Memory Expansion Support Options                    | 96        |   |            |