

# Peripherals and Accessories

For detailed information on these peripherals, please refer to the HP 3000 Series 900 Configuration Guide; available in the July 1993 edition, Publication Number 5091-7438E.

Peripheral, and accessory information in this document is for reference only. This information does NOT imply support on all SPUs

and operating systems.  
**All disk drive cabling must be ordered seperately.**

## Cabinet Storage Systems

Description	Capacity	Product No./ Option No.	PRICE
<b>STORAGE PRODUCTS FOR INSTALLATION INSIDE SPU PACKAGE</b>			
<b>3.5-inch Disk Drive</b>	1.0 Gb	<b>A2445A</b>	
Includes install by field CE		Opt. 001	<b>\$3,045.</b>
No field CE install included		Opt. 002	<b>2,845.</b>
<b>5.25-inch Disk Drive</b>	2.0 Gb	<b>A2446A</b>	
Includes installation by field CE		Opt. 001	<b>5,890.</b>
No field CE installation included		Opt. 002	<b>5,690.</b>
<b>5.25-inch Disk Drive (includes CE installation)</b>	677 Mb	<b>C2473S</b>	<b>4,800.</b>
Includes installation by field CE		Opt. 001	<b>4,800.</b>
No field CE installation included		Opt. 002	<b>4,600.</b>
<b>5.25-inch Disk Drive (includes CE installation)</b>	1.355 Gb	<b>C2474S</b>	<b>6,550.</b>
Includes installation by field CE		Opt. 001	<b>6,550.</b>
No field CE installation included		Opt. 002	<b>6,320.</b>
<b>3.5-inch DAT Tape</b>	2.0 Gb	<b>C2477SZ</b>	
Includes installation by field CE		Opt. 001	<b>2,700.</b>
No field CE installation included		Opt. 002	<b>2,500.</b>
<b>3.5-inch DAT Tape</b>	up to 8.0 Gb	<b>C2478SZ</b>	
Includes installation by field CE		Opt. 001	<b>3,700.</b>
No field CE installation included		Opt. 002	<b>3,500.</b>
<b>CD-ROM</b>	600 Mb	<b>C2476SZ</b>	
Includes installation by field CE		Opt. 001	<b>1,450.</b>
No field CE installation included		Opt. 002	<b>1,250.</b>
<b>INTEGRATED CABINET CONFIGURATIONS FOR 9x7 AND 99x AT THE FACTORY</b>			
<b>1100mm U 19-inch Computer Rack</b>		<b>A1883A*</b>	<b>\$1,890.</b>
U.S. 100 - 120V power		Opt. ABA	<b>N/C</b>
Add DTC 72 MX		<b>J2070AZ</b>	
Configure with 24 RS-232 direct connect RJ-45 ports		Opt. 001	<b>3,400.</b>
Configure with 48 RS-232 direct connect RJ-45 ports		Opt. 002	<b>6,800.</b>
Configure with 72 RS-232 direct connect RJ-45 ports		Opt. 003	<b>10,200.</b>
Replace 8 RJ-45 direct ports with 8 DB-25 modem ports		Opt. UG5**	<b>300.</b>
Add X.25 board with RS-232 interface		Opt. 1CW**	<b>2,400.</b>
Add X.25 board with V.35 interface		Opt. 1CX**	<b>2,400.</b>
Add Telnet Access board		Opt. 004**	<b>3,000.</b>
Racked DTC16iX LAN Manager		<b>J2062AZ**</b>	<b>2,160.</b>
Replace 8 direct with 8 modem ports		Opt. UG5**	<b>300.</b>
Add SCSI Disk (one 1.3 Gb disk drive)	1.3 Gb	<b>C2461AZ</b>	<b>5,720.</b>
Add SCSI Disk (two 1.3 Gb disk drives)	2.7 Gb	<b>C2462AZ</b>	<b>10,940.</b>
Add SCSI Disk (three 1.3 Gb disk drives)	4.0 Gb	<b>C2463AZ</b>	<b>16,160.</b>
Add SCSI Disk and One DDS Tape Drive	2.7 Gb	<b>C2464BZ</b>	<b>14,090.</b>
Add SCSI Disk (one 2.0 Gb disk drive)	2.0 Gb	<b>C3023RZ</b>	<b>6,990.</b>
Add SCSI Disk (two 2.0 Gb disk drives)	4.0 Gb	<b>C3024RZ</b>	<b>12,680.</b>
Add SCSI Disk (three 2.0 Gb disk drives)	6.0 Gb	<b>C3025RZ</b>	<b>18,370.</b>

Select appropriate language manual option when ordering (ABA, ABD, ABF, ABJ)

**Select a System Support Option. Refer to Table 4 on page 112. \* For A1883A, see Table 4.1 on page 116 for Support Options.**

\*\* Orderable July 1, 1993.