$\underline{\textit{Datacomm and Terminal Controller Products (DTC) (cont'd)}}$ 

Description	Product No./ Option No.	PRICE
DTC16iX LAN Multiplexer	J2062 <b>A</b>	\$2,160.
Replace 8 direct with 8 modem ports	Opt. UG5	300.
DTC72MX Communication Server	J2070A	2,800.
Racking kit for 1100mm and 1600mm racks	Opt. 1AC	N/C
24 RS-232 Direct connect ports	Opt. 001	3,400.
18 RS-232 Direct connect ports	Opt. 002	6,800.
2 RS-232 Direct connect ports	Opt. 003	10,200.
IP 3000 Telnet Access card	Opt. 004	3,000.
C.25/RS-232 Network Access card	Opt. 1CW	2,400.
C.25/V.35 Network Access card	Opt. 1CX	2,400.
24 RS-423 Direct connect ports	Opt. UG4	4,300.
Replace 8 direct with 8 modem ports	Opt. UG5	300.
4 RS-232 Direct Connect Card	J2076A	3,700.
Replace 8 direct with 8 modem ports	Opt. UG5	300.
24 RS-423 Direct Connect Card	J2077A	4,700.
HP 3000 Telnet Access Card	J2080A	3,300.
Modem Distribution Panel Racking Kit	J2084A	300.
Accessories for DTC16iX, 16TN and 72MX	J2085A	
-Port RS-232 Modem distribution panel	Opt. 101	350.
-Port RS-232 Direct distribution panel	Opt. 102	180.
4-Port RS-232 Direct distribution panel	Opt. 103	350.
- B-Port Multiport cable with HP 3-pin connectors	Opt. 104	180.
Racked DTC16iX LAN Multiplexer	J2062AZ	2,160.
Replace 8 direct with 8 modem ports	Opt. UG5	300.
Racked DTC72MX Communication Server	J2070AZ	2,800.
4 RS-232 Direct connect ports	Opt. 001	3,400.
8 RS-232 Direct connect ports	Opt. 002	6,800.
'2 RS-232 Direct connect ports	Opt. 003	10,200.
Replace 8 RJ-45 direct ports with 8 DB-25 modem ports	Opt. UG5	300.
Add X.25 board with RS-232 interface	Opt. 1CW	2,400.
Add X.25 board with V.35 interface	Opt. 1CX	2,400.
Add Teinet Access board	Opt. 004	3,000.
Add-On X.25 Network Access Card for DTC72MX	J2079A	N/C
Add-on X.25 RS-232 Interface card for DTC72MX	Opt. 1CW	2,700.
Add-on X.25 V.35 Interface card for DTC72MX	Opt. 1CX	2,700.
IP OpenView Windows Workstation Upgrade Software	D1824C	1,060.
Ipgrade to the OpenView Windows Workstation product (32054x)	2.02.13	1,225.
IP OpenView DTC Manager upgrade	Opt. 201	1,050.
IP OpenView System Manager upgrade	Opt. 202	350.
IP OpenView Switch/PAD Manager (1 - 4 nodes) upgrade	Opt. 204	1,750.
HP OpenView Switch/PAD Manager (5 - 10 nodes) upgrade	Opt. 205	3,150.
HP OpenView Switch/PAD Manager (10 nodes) upgrade	Opt. 206	4,690.
HP OpenView DTC Manager DTC management software for the PC. If HP OpenView Windows Workstation is ordered with HP OpenView DTC Manager Option (32054D, Opt. 201), this removes the need to order D2355A.	D2355A	1,575.

Select a System Support Option. Refer to Table 5 on page 143.