

MS-5163 W563MS41 BIOS Release

1. This is an AWARD BIOS ver 4.1 release.
2. This BIOS fixes the following problems of the previous version:
 - Fixed the problem of Cyrix 83.3Mhz CPU in which it will hang in Windows®95 when you click drive A.
 - Fixed Boot sequence problem.
 - Added Typematic Keyboard function.
 - Added support for SDMS 3.0.
 - Added boot up floppy seek function.
 -

** Please refer to FLASH.DOC for programming notes.