

■ **Hardware**

- ISA (EISA) and MCA bus formats
- S_{2M} (30B+D or 23B+D in NA and Japan)
- Intel 80486 with 33 MHz with 4MB on-board
- 8 MHz (according to IEEE P 996)

■ **Supported Standard**

Interfaces

- CAPI for DOS & OS/2
- CAPI DLL for Windows & OS/2
- Packet Driver for TCP/IP
- ODI
- NDIS (for DOS and OS/2)
- DLC/802.2 interface for DOS
- NABIOS
- WAN Miniport driver for Windows NT

■ **Connection Types**

- Switched & Permanent

■ **B-Channel Protocols**

- X.75 (LAPD)
- LAPD
- SDLC (SNA)
- transparent
- X.25 PLP (also in D-channel)
- T.90NL
- T.70NL
- Transparent

■ **D-Channel Protocols**

- E-DSS1 (Euro-ISDN)
- NI-1
- 1TR-6
- Japan
- 5ESS

- ATEL
- Other international protocols

■ **Workstation Requirements**

- CPU 80386
- At least 1 Mbyte of memory

■ **Supported OS Platforms**

- DOS
- Windows 3.x
- NetWre
- OS/2
- Windows NT
- UNIX

■ Packaging Contents

- S_{2M} Hardware
- DB15 Cable
- User Guide
- B and D Channel Trace Program
- IDI (ISDN Direct Interface)
- CAPI 1.1 & 2.0 (DOS)
- International D-Channel Protocol Software
- ACOPI

Ordering Information	
Product Name	Product Code
S _{2M}	310-188
Related [items]	
S _{2M} (MCA Version)	310-189
ISDN Server for Windows NT (S _{2M})	305-089
Connections for NetWare (ISDN Support for MPR & NetWare Connect)	314-644



Eicon Technology Corporation

Tel.: (514) 745-5500
Fax: (514) 745-5588

In the United States, Canada, Latin America:

Tel.: 1-800-80-EICON
(214) 239-3270
Fax: (214) 239-3304

In Europe, Middle East, Africa:

Tel.: +44 (0) 181 967-8000
Fax: +44 (0) 181 967-8050

In Australia, New Zealand, Asia:

Tel.: +61 (2) 9919-7200
Fax: +61 (2) 9929-6300

Internet:

North America: sales@eicon.com
Europe: sales.europe@eicon.com
Asia Pacific: sales.asiapac@eicon.com
Worldwide Web: <http://www.eicon.com/>



© 1996 Eicon Technology Corporation. All rights reserved.
All trademarks or registered trademarks are the property of their respective owners.