

Summary

The ADB could not be accessed. The error indicates a hardware problem.

Details

The main circuit board of your Mac contains circuitry that allows you to plug ADB (Apple Desktop Bus) devices into your computer through the ADB port on your system. That circuitry has failed.

What to do

You will have to replace the entire main circuit board of your computer to fix this problem.