

Sheet1

TYP,KCJEDNOTKY,C,20		KONSTANTA,C,15
AN	1 cm	1
AN	2 %	1
AN	3 S	1
CL	0 Pa	1
EJ	0 kW;kWh	1;1
EL	0 kW;kWh	1;1
PA	0 t/h;t	1;1
PA	1 MWh;MW	1;1
PA	2 GJ/h;GJ	1;1
PA	3 m ³ /h;m ³	1;1
PI	0 m ³ /h;m ³	1;1
PI	1 t/h;t	1;1
PI	2 GJ/h;GJ	1;1
RE	0 °C	0.1
RI	0 °C	0.1
RI	1 kPa	1
RI	2 m	0.1
RI	3 cm	1
RI	4 %	1
RI	5 MPa	0.001
RK	0 °C	0.1
RK	1 kPa	1
RK	2 m	0.1
RK	3 cm	1
RK	4 %	1
RK	5 MPa	0.001
TE	0 °C	0.1
TL	0 kPa	1
TL	1 MPa	0.001
PA	4 t/h;t	0.001;0.001
PA	5 GJ/h;GJ	0.001;0.001
PA	6 GJ/h;GJ	1.0e-6;1.0e-6
TL	2 bar	0.01
HR	0 kW;kWh;kVAr;kVArh	1;1;1;1
KC	0 kPa	1
RM	0 °C;t°C	0.1;10